



- * Send R99 PACKET MEASUREMENT REPORT message.
- ** Send R97 PACKET MEASUREMENT REPORT message.
- *** Send R99 PACKET MEASUREMENT REPORT message with new field 'NC_MEAS_LIST_TYPE'